

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EW750
East
> 1
1.045 mi.
5519 ft.

MANHOLE #1578
CONEY ISLAND AVE/BRIGHTON
BROOKLYN, NY

NY Spills **S105058104**
N/A

Site 3 of 5 in cluster EW

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: VAULT 6503
Address: CONEY ISLAND AVE/BRIGHTON
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0102774 / 2001-07-20
Facility ID: 0102774
Facility Type: ER
DER Facility ID: 119145
Site ID: 139463
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2001-06-12
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2001-06-13
CID: 211
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-13
Spill Record Last Update: 2001-08-20
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: RICHARD ROACH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS REPORT 6-12-01 While on location to install new transformer, found 1pt. unknown oil on 300gals. of water in VS-6503. There is no transformer in this structure at this time. Transformer was removed on a 4-25-01 as per previous incident #136648. PCB results at that time were <1ppm (LSN 01-05169-001) There is a sump in the structure which was found disconnected. LSN 01-06466-001 Aroclor 1260: PCB <1ppm 0952hrs. Structure filled to top with water and tanker is not on location to complete job. 1245hrs. tanker removed all liquids from structure. Found cement sump in structure. No leaking company equipment. No samples required, double washed structure with slix. Env. tag removed."
Remarks: "1 PINT OF PRODUCT ON 300 GALS WATER - SAMPLE TAKEN LESS THAN 1 PPM PCB - CON ED 137611"

All Materials:

Site ID: 139463
Operable Unit ID: 839398
Operable Unit: 01
Material ID: 534883

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: MANHOLE #1578
Address: CONEY ISLAND AVE/BRIGHTON
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0201853 / 2002-09-23
Facility ID: 0201853
Facility Type: ER
DER Facility ID: 119145
Site ID: 139464
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2002-05-20
Investigator: AERODRIG
Referred To: Not reported
Reported to Dept: 2002-05-21
CID: 297
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-05-21
Spill Record Last Update: 2002-09-23
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: KEVIN MCARDLE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ E2MIS NOTES 142887 5-20-02 17:25HRS R. VEGA (ENV OPS) REPORTS, FOUND ONE QUART OF UNKNOWN OIL ON 10 GALLONS OF WATER IN MH1578. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE AFFECTED. NO FIRE - SMOKE OR PRIVATE PROPERTY WAS INVOLVED AND NO INJURIES WERE RELATED TO SPILL, AND NO WEATHER CONDITIONS CONTRIBUTED TO HAZARD OF SPILL. OIL WAS DISCOVEREDWHILE ON ROUTINE WORK FOR U.G. NO OTHER OIL FILLED EQUIPMENT SEEMS TO BE LEAKING IN STRUCTURE AND THE WATER THAT ISM PRESENT HAS NO MOVEMENT. ENV STOP TAG# 35039 WAS PLACED, AND NO SEWER CONECTIONS OR SUMPS CAN BE VARIFIED AT THIS TIME BECAUSE OF LUMBER IN STRUCTURE. ONE LIQUID SAMPLE WAS TAKEN ON A E PRIORTY AND CLEANUP WILL BE PENDING LAB SAMPLE. UPDATE: 5/20/02 - 2015 A. WALKER - O.S. - ENV. OPS., REPORTS SAMPLE DELIVERED TO CHEM LAB. 5/20/02=2351 LAB RESULTS RETURNED

<1.PPM LSN-04553 Update - 5/21/02 0230hrs K. Hufford , env. ops reports removed liquids with vactor and double washed with bulldog.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Remarks:

Found earthen sump in structure and sealed same with cement. No leaking co. equipment. Removed env. stop tag # 35039. Incident completed."

"WORKERS FOUND APPROX 1QT OF AN UNKNOWN OIL FLOATING ON 10 GALS OF WATER - SPILL HAS BEEN CLEANED UP / CONED SPILL #142887"

All Materials:

Site ID: 139464
Operable Unit ID: 852822
Operable Unit: 01
Material ID: 523268
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Oxygenate: Not reported